Distribution is not authorized outside of the GIDEP participant's organization. TAB 17

| GOVERNMENT - INDUSTRY DATA EXCHANGE PROGRAM  ALERT   |   |                                    |              |
|--|---|------------------------------------|--------------|
| 1. TITLE (Class, Function, Type, etc.)   |   | 2. DOCUMENT NUMBER                 |              |
| , , , , , , , , , , , , , , , , , , ,  |   | GG5-A-11-001                       |              |
| Suspect Counterfeit, Microcircuit, 256K x 16 Bit CMOS Video RAM  |   | 3. DATE (DD-MMM-YY)                |              |
| , ,  |   | 20 December 2010                   |              |
| 4. MANUFACTURER AND ADDRESS 5. F   | ART NUMBER 6. NATIONAL STOCK NUMBER   |                                    | NUMBER       |
| Samsung Semiconductor Inc.   | 14216C258G-50   | FICATION 8. GOVERNMENT PART NUMBER |              |
|  | SPECIFICATION   |                                    |              |
|  | t Available   |                                    |              |
|  | LOT DATE CODE START   |                                    |              |
| 08   | • =   | 0813                               |              |
|  | CAGE  | 13. MANUFACTURER'S FAX             |              |
|  | t Applicable  | Not Applicable                     |              |
|  | MANUFACTURER'S E-MAIL   |                                    |              |
| • •  | Applicable Supplier address 18. Supplier cage   |                                    |              |
|  | SUPPLIER ADDRESS  |                                    |              |
| Withheld Wii  19. PROBLEM DESCRIPTION / DISCUSSION / EFFECT  | nheld   |                                    | Withheld     |
| subjected to counterfeit inspection and analysis at an independent L-3 approved test facility with no obvious signs of suspect/counterfeit characteristics observed.  High failure rate during testing prompted L-3DS to conduct further testing. New suspect components with data code 0813 were sent to a different L-3 approved test facility, which detected multiple abnormalities during testing (full report attached). Based on these abnormalities components with date code 0813 have failed inspection and are not considered to be factory original parts.  Note: The manufacturer identified in block 4 is the entity whose product may have been counterfeited. This reporting convention is necessary to facilitate GIDEP database searches for suspect counterfeit products and is by no means intended to imply that the manufacturer identified in block 4 is involved with the suspect product. |   |                                    |              |
| All components with the 813 date code have been quarantined at L-3's facility. All parties that have received the suspect components from L-3 Display Systems have been contacted regarding the suspect components. In addition, L-3 will replace all suspect components supplied in fielded units through a process of attrition.   |   |                                    |              |
| 21. DATE MFR. NOTIFIED/ SUPPLIER NOTIFIED  REPLY ATTACHED  Not Applicable  No REPLY  NO REPLY  22. MFR./SUPPLIER RESPONSE  REPLY ATTACHED  NO REPLY  24. GIDEP REPRESENTATIVE  | 23. ORIGINATOR ADDRESS/POINT OF CONTACT  Mike Meo, L-3 Communications Display Systems 1355 Bluegrass Lakes Pkwy  Alpharetta, GA 30004  @L-3com.com  25. SIGNATURE  26. DATE |                                    |              |
| Mike Meo   | Mile M  | <b>ی</b>                           | 15 Dec. 2010 |

GIDEP Form 97-2 (September 2009)

Please refer to the complete distribution policy at the GIDEP member's website.